PRODUCT BULLETIN

Date	20/09/2021
PRODUCTS AFFECTED	
PART NUMBER	104-082B
PRODUCT/S	Hikvision TVI DVRs, various models. Current Ness Part No. 104- 082B
AFFECTED FIRMWARE	V4.21.102, V4.20.102, V4.21.004
ISSUE	The DVR allows auxiliary IP Cameras (IPC) to be added and operate normally however the IPC will be offline and all configurations lost after DVR reboot. All channel parameters must be reconfigured.
DETAIL	
REMEDY	Upgrade the DVR firmware then reconfigure the IPC(s) <u>https://drive.google.com/file/d/1OPJ8a5_rlJaMCSvhFWpFBJf8rsG9</u> <u>6YZR/view?usp=sharing</u>
NOTE	The DVR in question has 16 Analogue video channels which are unaffected. This notification applies only to IP cameras configured on the DVR.

www.ness.com.au

Ness Corporation Pty Ltd ABN 28 069 984 372 Private Bag 23 Seven Hills NSW 1730 Australia Ph +61 2 8825 9222 Fax +61 2 9838 8508 Email: ness@ness.com.au



Sydney 4 / 167 Prospect Hwy Seven Hills NSW 2147 Phone 02 8825 9222 Fax 02 9674 2520 sales@ness.com.au Melbourne 4 / 56 Norcal Rd Nunawading VIC 3131 Phone 03 9875 6400 Brisbane Unit 5 / 16 Metroplex Ave Murarrie QLD 4172 Phone 07 3399 4910 Adelaide Unit 1 / 22 Ware St Thebarton SA 5031 Phone 08 8152 0000 Perth 1 / 9 Inverness St Malaga WA 6090 Phone 08 9328 2511

nessmelb@ness.com.au ness

nessbris@ness.com.au adelaid

adelaide@ness.com.au nessper@

nessper@ness.com.au