

PRODUCT NOTICE FOR NESS RK5 RADIO KEY

09/07/2026

OVERVIEW

Ness RK5 Radio Key when used on DPlus control panels via 106-462 X-TWR Interface cannot operate AUX2 output on the DPlus panel.

PRODUCTS AFFECTED

106-462 X-TWR Radio Interface
V1.42 and earlier

SOLUTION

Replace the 106-462 X-TWR Radio Interface with V1.43 or later.



Innovative Electronic Solutions
www.ness.com.au



NSW Ph 02 8825 9222
sales@ness.com.au

VIC Ph 03 9875 6400
nessmelb@ness.com.au

QLD Ph 07 3399 4910
nessbris@ness.com.au

WA Ph 08 9328 2511
nessper@ness.com.au

SA Ph 08 8152 0000
adelaide@ness.com.au

© Ness Corporation Pty Ltd ABN 28 069 984 372. Photos are used for illustrative purposes only. Design and specifications may vary. See the Ness Corporation web site for full warranty details.